



PIN 1 and 2 of M4 need to be swapped
 best to install M4 upside down, with leads folded down to make contact
 with PCB pads
 M4 only mounted when using the 12V boost supply for OLED displays